


Connect the PSM to input channel 1 from the loop input to 0V and connect input channel 2 from the loop output to 0V. The PSM inputs are fully floating and do not need external isolation.



Simplified schematic of a switching power supply showing connections for loop stability measurements

Setting the amplitude




It is important that the generator amplitude is set to a suitable level so that the signals can be measured reliably but the control loop is not overdriven.

Put the PSM into gain/phase analyser mode (press FUNC or use MODE menu on the PSM2200, or press FRA on the PSM1700/35).

Using the OUT menu, set the generator to a frequency at the lower part of the control loop bandwidth, set minimum amplitude (enter 0 and the minimum will be inserted), and turn on the output. Either by looking at the measurement on CH2 or by using an oscilloscope connected to the output, slowly increase the amplitude of the generator (using UP key or OUT menu) until a small but stable signal is present on CH2.

Having found an appropriate signal level, enter the measured value from CH1 in the 'ac level' field of the TRIM CONTROL menu (press OUT then NEXT on the PSM2200 or use trim menu on the PSM1700/35). Set the 'ac trim data' field to CH1 and set the 'tolerance' field to 10% or 20% if the signal is very low. This will ensure that all frequencies are tested with a similar level of disturbance; the PSM will automatically adjust the generator amplitude to meet the trim criteria (this technique is also known as amplitude compression).

This can be an important feature as the same generator level used at all frequencies may present problems. Consider the three vectors – disturbance amplitude (generator), CH1, and CH2 – as shown in figure a. As these form a complete loop, if the disturbance amplitude is not adjusted (by controlling the generator), then the loop input signal is effectively increased as the gain of the system reduces (figure b), and the loop is likely to be overdriven:



By controlling the generator signal to maintain a constant loop disturbance (amplitude compression controlled by CH1, figure c), overdriving of the control loop can be avoided. By setting the TRIM CONTROL parameters appropriately, the PSM can provide the amplitude compression function automatically as the frequency is changed. The PSM unit makes an audible beep when the generator amplitude is adjusted.

Try a few frequency points manually (use LEFT/RIGHT keys or OUT menu) to verify that the generator can be adjusted appropriately and that the control loop is not overdriven.

Making the measurements

Set the frequency range of interest for the sweep (press SETUP then NEXT on the PSM2200 or SWEEP mode on the PSM1700/35) and press START to begin the frequency sweep. The results may be viewed on the screen as a table or graph using the DISP key on the PSM2200 or TABLE and GRAPH keys on the PSM1700/35. When viewing the graph, a cursor may be moved across the screen using the LEFT and RIGHT keys.

All PSM units are fully operable by communications over RS232 and the results read back as comma delimited ASCII data (refer to manual for commands). The data can then be imported into an application for inclusion in reports and all units can be controlled by N4L dedicated control software.

Hints and tips

If the signals are very noisy, or if the level has to be kept very small to prevent overdriving the control loop, select 'slow' speed in the SETUP menu. This will have the effect of slowing the sweep (~2.5 seconds per point) but increases the selectivity of the measurement.

The measured phase may be displayed either in the range of 0° to 360° , or -180° to $+180^\circ$. Set the convention to be used in the SYSTEM menu.

The settings may be stored in any of the non-volatile program locations 1-100, then recalled when needed.

Testing loop stability	525-002	Issue 5
Newton4th Ltd 30 Loughborough Rd Mountsorrel Loughborough LE12 7AT UK Tel: +44 (0)116 2301066		